# MetalSkin<sup>®</sup> Cased-Hole Liner Enables Deployment on Coiled Tubing to Save 3 Days of Rig Time

## **Objectives**

- Overcome a casing integrity issue and high pressure that prevent the pumping of frac plugs to the desired depth and increase the risk of a blowout in a Marcellus natural gas well. The operator suspected that a parted collar caused the problems.
- Complete the repair under tight time constraints to make use of the frac crew during its short scheduled period.
- Enable finishing 18 of 30 stages in a fracturing operation with pumping pressures of more than 10,000 psi (68.945 Mpa).

# **Our Approach**

- Weatherford first used wireline to run a caliper log, which confirmed the parted collar as the cause of the pressure.
- Weatherford designed a high-pressure casing repair procedure that accommodated the lubricator on location, facilitated deployment, and enhanced equipment integrity and personnel safety in this potentially volatile situation.
- Because of the 4,000 psi (27.58 Mpa) well pressures on the small location, the Weatherford crew deployed a coiled-tubing-conveyed, full-wrap, highpressure MetalSkin cased-hole liner system. The system eliminated the need for time-consuming tool modifications, additional rig equipment, and drillout after expansion.
- The MCL was pressure tested to 10,000 psi (68.945 MPa) once the tools were removed.
- The quick deployment met the short timeline for repairing the wellbore, finishing the fracturing operation, and ultimately completing the well.

### Value to Client

- The MetalSkin cased-hole liner system remediated the parted collar and reduced the high pressures in a single run. The system enabled the operator to complete the repair quickly, before the redeployment of the fracturing crew.
- The liner system eliminated the need to drill out a shoe, and deploying the system on coiled tubing required no additional equipment. The post-expanded ID of the MCL allowed the frac crew to continue a planned plug-and-perf operation, and the full wrap enabled them to stay within the treating pressure. Thus, the crew completed the operation 3 days earlier than planned.
- The operator was able to immediately return to fracturing operations and complete the 18 remaining stages on time.



The Weatherford coiled-tubing-conveyed MetalSkin cased hole liner enabled the operator to complete fracturing operations in a short time frame in a natural gas well.

LOCATION Northeast Pennsylvania

FORMATIONS Marcellus Shale

**RIG TYPE** Coiled tubing

WELL TYPE Natural gas

HOLE ANGLE Vertical

**CASING TYPE AND SIZE** 5 1/2-in., 23-lb/ft casing

**MEASURED DEPTH** 6,766 ft (2,062 m)

PRODUCTS/SERVICES 4.25-in. × 5.50-in. MetalSkin cased-hole liner



MetalSkin is a registered trademark of Weatherford in the US and United Kingdom

#### weatherford.com

© 2016 Weatherford. All rights reserved. 12612.00

Weatherford products and services are subject to the Company's standard terms and conditions, available on request or at weatherford.com. For more information contact an authorized Weatherford representative. Unless noted otherwise, trademarks and services marks herein are the property of Weatherford and may be registered in the United States and/or other countries. Weatherford products named herein may be protected by one or more U.S. and/or foreign patents. Specifications are subject to change without notice. Weatherford sells its products and services in accordance with the terms and conditions set forth in the applicable contract tetweenes with exist.